

The Remaining To Fill display shows how much more weight is required to reach the desired weight. When this weight is keyed in, the scale tracks the filled weight and shows the remaining amount. If the user exceeds the desired weight, an excess indicator shows how much needs to be removed.

< <u>Previous</u> | <u>Next</u> >